#2104 PUMP STATION 4002 REHAB (25% - SEPTEMBER 2024)



- 1. D Construction LLC (PopCo Subcontractor) Crewmembers work on the interior masonry wall formation for the instrumentation and control room.
- 2. James Merrit (PopCo Superintendent) inspects the masonry work and wall preparation activities for the upcoming interior stucco repairs.
- 3. Southeast view of the existing pump station construction activities existing door to be replaced, and windows are removed and blocked up.