

Facility Construction Project Photos – August 2024

#2108 PUMP STATION 4001 REHAB (0% - SEPTEMBER 2024)



1. Post-Tropical Storm Debby inspection, PS4001 on JWSC sewer bypassing to assist with high levels in wetwell.
2. Northbound view from the backside of the Pump Station 4001 project site.
3. PopCo is working with EMC to secure the instrumentation and control materials.