

## Facility Construction Project Photos – August 2024

#2104 PUMP STATION 4002 REHAB (50% - SEPTEMBER 2024)



1. Post-Tropical Storm Debby inspection, PS4002 on JWSC sewer bypassing to assist with high levels in wetwell.
2. Eastbound view from the backside of the Pump Station 4002 project site.
3. Instrumentation and Controls work pending the delivery of the electrical components before the existing equipment is taken offline and the system placed on JWSC sewer bypassing.