

Facility Construction Project Photos – November 2024



- 1. Bio-Nomics Operator is preparing PreCCTV activity near 1828 Lee Street.**
- 2. Bio-Nomics Operators perform routine maintenance and cleaning for service lateral ball cutter.**
- 3. Bio-Nomics Operator performs CIPP liner temperature checking during curing.**
- 4. CIPP 8-inch liner installation at the intersection of Union Street and London Street.**