

Facility Construction Project Photos – October 2024



1. Drone view of construction activities at the Academy Creek WPCF.
2. Drone view of the construction activities at the UV channels—Reeves Young's demolition of the concrete walls, beams, and columns on the west bank is nearly completed.
3. Southbound view of the RAS building #1 Pump Room.
4. View of the UV Channels walls, beams, and columns removed and awaiting disposal.
5. Various piping and fittings are stored at the Academy laydown yard.
6. Various piping and RAS pump stands are stored at the Academy laydown yard.