

## Facility Construction Project Photos – October 2024



- 1. Post Hurricane Helene & Milton Inspection – no site issues or storm damages to report.**
- 2. JWSC SPMD secondary bypass pump delivered onsite in preparation for Instrumentation upgrades.**
- 3. PS4002 electrical control, VFDs, and Scada panels onsite, installation pending sewer bypassing.**
- 4. View of existing Instrumentation and Control Room – control panels to be removed and replaced.**